

Updated 1/25/2022

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Dynasty	10249	54103 (Mister)							
Balboa	1000LER1(x)	52491	59-138-1005	58-138-1148	59-138-1075	59-138-1070	On Board	On Board	Takes any Duplex panel, NON-M7
Keys Backyard	100CR1(x)	54369-01							
Keys Backyard	100DR1(x)	54369-01							
Coleman	105/7R1(x)	51666	No Generic	58-138-1148*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	*Proprietary Label
Coleman	10R1(x)	51118	59-138-1033	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	
Coleman	115/7R1(x)	52336							
Coleman	120R1(x)	50803	59-138-1025	58-138-1100	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Coleman	135R1(x)	52709-01	*59-138-1037		59-138-1070	59-138-1070	On Board	On Board	*Can use 59-138-1037 but will need to replace with generic topside label
Coleman	137R1(x)	52709-01	*59-138-1037		59-138-1070	59-138-1070	On Board	On Board	*Can use 59-138-1037 but will need to replace with generic topside label
Cal Spa	15001R1(x)	52935	*59-355-1049		59-138-1060	59-138-1060	59-138-1260	59-138-1262	*Verify they have two button topside Jet/Light and Temp
Cal Spa	15002R1A	52938							
GPM	150E	53220	59-138-1033		59-138-1060	59-138-1060	On Board	On Board	
Emerald/Conway	150ER1(x)		59-138-1033	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	
Morgan	150R1(x)	50745	59-138-1035*	58-138-1110*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Needs Auxiliary Phone Jack Installed
Morgan	150R2(x)	50895			59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Thermo Spas	1900DR1(x)	51405	59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Thermo Spas	1900R1(x)		59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	51230 Low Speed is only when call for heat on generic
Thermo Spas	2000DR1(x)	51408	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	Will lose lock function, topside is a 7 button Serial Standard.
Thermo Spas	2000DR2(x)	51408	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	Will lose lock function, topside is a 7 button Serial Standard.
Balboa	2000LEM7	53563-01							
Balboa	2000LER1(x)	52295	59-138-1007	58-138-1102-1104	59-138-1075	59-138-1070	On Board	On Board	NON M7
Balboa	2000M7R1(x)	52320	59-138-1043	58-138-1102-1104	59-138-1070	59-138-1070	On Board	On Board	M-7 Style
Balboa	2000P3R1A	52914	59-138-1008	58-138-1102-1103-1104	59-138-1075	59-138-1070	On Board	On Board	3 Pump system
Thermo Spas	2000R1(x)		59-138-1025	58-138-1100	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Thermo Spas	2000R1(x)		59-138-1025	58-138-1100	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Great Lakes/GPM	2002LER1(x)	52295	59-138-1007*		59-138-1075	59-138-1070	On Board	On Board	Stereo function will discontinue with the use of this board
Coleman	200R1(x)	50804	59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Coleman	200R2(x)	51084			59-138-1060	59-138-1060	59-138-1250	59-138-1252	Digital - Phone Style Connector
Coleman	200R2(x)	51092	59-138-1025*		59-138-1060	59-138-1060	59-138-1250	59-138-1252	Analog - Ribbon cable
Coleman	200R2(x)	51091	59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Standard Digital - Ribbon cable
Cal Spa	2100R1(x)	52299	No Generic	58-138-1148*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Board uses Kidney Shaped Topside The 58-138-1148 will work there will be a small light on the temp display when heater is on and the safety suction light will not be there.
Keys Backyard	211DR1B	53753-01/02	59-138-1684*		59-138-1070	59-138-1070	On Board	On Board	*Must use new OVERLAY 58-138-1265
Marquis Spa	21862R(B)	53579							Marquis # 600-6289
Cal Spa	2200R1(x)	52195	No Generic		59-138-1075	59-138-1070	On Board	On Board	Board uses Kidney Shaped Topside
Cal Spa	2300R1(x)	52195	No Generic		59-138-1075	59-138-1070	On Board	On Board	Board uses Kidney Shaped Topside

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Beachcomber	2500ESR1(x)	54003	59-138-1042	58-138-1146-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Other Topside 58-138-1142,1144,1165 Does not work if 2 button topside is used
Beachcomber	2500ESR2(x)	53210-02	No Generic*						*Replaced by 2500ESR1(x) when you replace with a new topside as well.
Beachcomber	2500ESR2(x)	53210	59-138-1042						
GPM	260 /410E	51421							
Sonoma	2M7DLXR1(x)	53339			59-138-1070	59-138-1070	On Board	On Board	
Alps Spa	2M7P3R1(x)	53563-01*	No Generic		59-138-1070	59-138-1070	On Board	On Board	2000LE 3 pump special
Swim Spa	2MP73R1(x)	53563							
Coleman	30XR1(x)	50968							
Great Lakes/GPM	3R1(x)		59-138-1046		59-138-1070	59-138-1075	On Board	On Board	
Coleman	400R1(x)	51764	No Generic		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Coleman	400R1(x)	51094							
Coleman	400R2(x)	51095	No Generic		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Coleman	400R3(x)	51764	No Generic		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Great Lakes/GPM	410ER1(x)	51421	59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Great Lakes/GPM	510ER1(x)	51509	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Coleman	512/4R1(x)	52357							
Coleman/Maax	516R1(x)	52547							
Great Lakes/GPM	520ER1(x)	54644	59-138-1031*	58-138-1180,1182,1104,1102	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Can run 2 2spd pumps or 1 2spd & 1 1spd with circ. (also used in Streamline Spas)
Thermo Spas	5500R1(x)		59-138-1025	58-138-1100	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Aquatic Eng.	6300DR1(x)	54003	59-138-1042	58-138-1146-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Other Topsides 58-138-1142,1144,1165
Aquatic Eng.	6300R1(x)	51230	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Coleman	630R1(x)	52717	No Generic		59-138-1070	59-138-1070	On Board	On Board	
Aquatic Eng.	6400R1(x)	50804	59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Aquatic Eng.	6500R1(x)	50788	59-138-1035	58-138-1110*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Single Speed Blower
Balboa	6U2	50162	59-138-1010	58-138-1101	59-138-1050	Mechanical	59-138-1250	59-138-1252	624pcb
Balboa	6UR	50179	59-138-1000	58-138-1101	59-138-1050	Mechanical	59-138-1250	59-138-1252	
Coleman	704/6R1(x)	52341			59-138-1060	59-138-1060	59-138-1250	59-138-1252	Board Runs Different Topside Looks like an M2\M3 Board
Coleman	70R1(x)		59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Coleman	736R1(x)	52719	No Generic		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Balboa	7XXG9R1(x)	50795	59-138-1020	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	7xx represents all numbers, Mainly 724 Series
Southwest Spa Leisure System Aquatics	850R1(x)		59-138-1020	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Grecian	9000R1(x)		59-138-1035	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Caldera	9100CP	51287	59-138-1656		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9100R1(x)	50769	59-138-1655	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	or use 59-138-1035
Caldera	9110R1(x)	50768	59-138-1657	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	or use 59-138-1030 single speed blower
Caldera	9115R1(x)	50759	59-138-1658	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	or use 59-138-1030 single speed blower
Caldera	9120R1(x)	50770	59-138-1659	58-138-1100	59-138-1060	59-138-1060	59-138-1250	59-138-1252	or use 59-138-1025

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Caldera	9130PMR1(x)	51366	59-138-1661	58-138-1150	59-138-1060	59-138-1060	On Board	On Board	
Caldera	9130R1(x)	51364	59-138-1660	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	or use 59-138-1040
Caldera	9600CP	51287	59-138-1656		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9610LA	51414	59-138-1031		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9610R(x)	51414	59-138-1031		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9615R(x)	51414	59-138-1031		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9700CP	51287	59-138-1656		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9710CP	51536	59-138-1664		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9710CP	51536	59-138-1664		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9710R(x)	51512	59-138-1663		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9715R(x)	51512	59-138-1663		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	9800CPR2(x)	51823	59-138-1665	Special Instructions*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Can use multiple topsides. Simply move the 50/60HZ jumper
Majestic Spa	AC100R1(x)	54122	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Alps Spa	ALP2M7R1(x)	53435	59-138-1043	58-138-1102 58-138-1104	59-138-1075	59-138-1070	On Board	On Board	
Alpine	ALP50R1(x)	54003	59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Balboa	ANALOGR1(x)	50803	59-138-1025	58-138-1100	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
American Pool	APS100R2(x)	52518	59-138-1031	Special Instructions*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Original board can have ribbon or ph style topside PH 58-138-1102 Ribbon 58-138-1105 New board uses 58-138-1102
Cal Spa	Auxillary Board	53681							
Streamline	B110DP	53192							
Streamline	B120DPR1(x)	51256	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Streamline	B240DGR1(x)		59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	3 Pumps - no generic / 2 pump use 59-138-1030
Streamline	B240DGR2(x)	50892	59-138-1031	Special Instructions*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Original Board 59-138-1652, Topside 58-138-1102-1104
Streamline	B2D6DPR2(x)		No Generic						
Streamline	B2DGDPR2(x)	53183	59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Streamline	B70R1(x)		No Generic						
Clearwater	BC2003R1B	52868							
Clearwater	BCHPR5R1(x)		No Generic						
Bullfrog	BF01R1(x)	59003	59-138-1019						
Bullfrog	BF05R2(x)	53984	59-138-1022*		59-138-1070	59-138-1070	On Board	On Board	*This board will work if not using any Audio or Video appliances
Blue Falls	BF100R1(x)	53024							
Blue Falls	BF75R1(x)	54003	59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Hawkeye	BH50D		59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Hawkeye	BH50D		59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Streamline	BSDGDPR1	53183							
Seven Seas	BSEV50		59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Sunrise	BSUN50D		59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Bullfrog	BULF20R1A	52182							
Bullfrog	BULF40R2C	51799							
Bullfrog	BULF60R1(x)	51959							

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Bullfrog	BULF65R1(x)	52392	No Generic	58-138-1146-1148	59-138-1075	59-138-1070	On Board	On Board	Board is a 1000LE M7 Style special order only
Bullfrog	BULF70R1(x)	52388	59-138-1043		59-138-1070	59-138-1070	On Board	On Board	
Cal Spa	C1000R1(x)		59-138-1033	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	
Cal Spa	C11JDR1(x)	51586	59-138-1042*	58-138-1147*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Replacement board will need replacement topside.
Cal Spa	C11JDR1(x)	51586	59-138-1042*	58-138-1147*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Replacement board will need replacement topside.
Cal Spa	C2000R2(x)	51987	No Generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	Board uses Kidney Shaped Topside (Also Safety Suction Switches)
Cal Spa	C2100R1(x)	52299	No Generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	Board uses Kidney Shaped Topside (Also Safety Suction Switches)
Cal Spa	C3001R1								Discontinued
Catalina	CAT100R1(x)	51692	59-138-1045	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Can use any Duplex Panel - No Fiber Optic
Catalina	CAT102R1(x)	52156							
Catalina	CAT200R1(x)	51678	59-138-1676	58-138-1115	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Catalina	CAT75R1(x)	52316	59-138-1674		59-138-1062	59-138-1061	On Board	On Board	
Catalina	CAT800M2R1(x)	53391/53250							Can use 59-138-1027 "Must verify W14 transformer wire on correct voltage"
Catalina	CAT800R1A-B	53858-02							Can use 59-138-1027 "Must verify W14 transformer wire on correct voltage"
Comfort Spa	CLP50R1A	51003							
Marquis Spa	COASTLR1(x)	54052	No generic						
Cal Spa/Coleman	COLE2PDVR1A								ELE09100232
Cal Spa	CS1100R1(x)	50929	No Generic	Special Instructions*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Sale a 59-138-1042, and a Mini-oval 58-138-1165 to retro fit, Only on one 2 speed pump option
Cal Spa	CS11GDR1(x)	51043	No Generic	58-138-1150	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Cal Spa	CS11GDR2(x)	51589							
Cal Spa	CS2000R1(A-F)	50865	59-138-1042*	58-138-1146-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Make sure topside is not Kidney Shaped may use Safety Suctions Switches
Cal Spa	CS2000R2(x)	51770	No Generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	Board uses Kidney Shaped Topside (Also Safety Suction Switches)
Cal Spa	CS2001R1(x)	51470	No Generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	Board uses Kidney Shaped Topside (Also Safety Suction Switches)
Cal Spa	CS2205R1(x)		No Generic		59-138-1075	59-138-1070	On Board	On Board	European Board uses Kidney Shaped Topside
Cal Spa	CS3000R1(x)	50862	59-138-1031	58-138-1102*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	If using oval topside replace with 1102,1103,1104
Cal Spa	CS3001R1(x)	51467							
Cal Spa	CS4000R1(x)	54122	59-138-1031	58-138-1115	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Cal Spa	CS4001R1(x)	51464							
Cal Spa	CS5000R1(x)	52299	59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Cal Spa	CS5300R1(x)	53632							
Cal Spa	CS6200R1A	53991-03							
Cal Spa	CS6300R1A	53993							
Cal Spa	CS9000R1A	52691							
Cal Spa	CS9000R2A	53304							
Marquis Spa	CSTL12R1(x)		No Generic						
Dynasty	D1000R1(x)		No Generic						
Dimension One	D1AR1I	50709	59-138-1610	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Dimension One	D1AR2(x)	51520	59-138-1611	58-138-1102-1104	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Topside Needs Verification
Dimension One	D1ARIF	50709	59-138-1610	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Dimension One	D1DR1(x)	50688	59-138-1608	See Notes	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Topside is 54036
Dimension One	D1PR2(x)	51520	59-138-1611	58-138-1102-1104	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Topside Needs Verification
Dimension One	D1SLR1(x)	51491	59-138-1653		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Dimension One	D1SR1(x)	51485	59-138-1615		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
LE Spa	D24R1(x)		59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Dynasty	D300R2(x)	***	No Generic						*** Can be replaced with new board 59-138-1031 and topside 58-138-1182
Dynasty	D400R1(x)	52914	59-138-1008				On Board	On Board	
Dakota Spas	DAK100R1(x)	51545	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Dakota Spas	DAK100R2(x)	51836							
Dakota Spas	DAK25R1(x)	51937	59-355-1049		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Dakota Spas	DAK50R1(x)	51542	59-138-1042		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Balboa	DELUXER1(x)	50805	59-138-1035	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Balboa	DIGDUPR1(x)	54003	59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Any Digital Duplex topside will work
Generic	DLX240	52518	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Diamond Spa	DS100R1(x)	54122	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Emerald/Conway	DS2	51035							
Emerald/Conway	DS34R1(x)	50680	59-138-1035	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Emerald/Conway	DS34R2(x)	50874-01	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Emerald/Conway	DS4R3C	52014	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Diamond Spa	DS50R1(x)	51542	59-138-1042	*See notes*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Filter Cycles Different, If customer has ribbon cable they will have to buy new topside as well 58-138-1148,1147,1149,1146
Grecian	DSWIMR1(x)	53103	53103	58-138-1110*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Same topside different label the temp buttons are in a different location
Streamline	DUB120DPC		59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Balboa	DUPLEXR1(x)	51230 50669	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1260	
Dynasty	DYN100R1E	51569	59-138-1042	58-138-1148*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Original Topside was a duplex oval, use a rectangle same hole size
Dynasty	DYN100R1(x)	51569	59-138-1042	58-138-1148*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Original Topside was a duplex oval, use a rectangle same hole size, can only be used for non circ pump systems. If they have a circ pump they must have original.
Dynasty	DYN300R1(x)		No generic						
Dynasty	DYN75R1(x)	51555	No Generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Balboa	EL1000 Mach2	53786							
Clearwater	EL1000R1A	53372							
Balboa	EL2000_Mach2	59003							
Balboa	EL2000_Mach3	53834-04	59-138-1022*		59-138-1070	59-138-1070	On Board	On Board	"When using 59-138-1022 to replace 53834-04 move the W15 wire to the J97 position and Dip Switches B1 B2 B3 all in the ON position."
Balboa	EL2001_Mach3	53974-04							
Diamondback Spas	EL2001R1(x)	53414	59-138-1023	58-138-1050	59-138-1070	59-138-1070	On Board	On Board	

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Balboa	EL2001R1C Mach 2.1	53414							
Balboa	EL2KELGSR1(x)	55313							
Balboa	EL8000 Mach2	52888-01							
Balboa	EL8000M3R1A (Mach3)	55214							
Balboa	EL8000R1B (Mach3)	53858/52640							Can use 59-138-1027 "Must verify W14 transformer wire on correct voltage"
Cal Spa	ELE09400340	54103 (mister)							
Clearwater	ELITER1(x)		59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Emerald/Conway	ES71R1(x)	50678	59-138-1035	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Emerald/Conway	ES72R1(x)	50679	No Generic						
Balboa	Expander Board	55137							
Balboa	Expander Board	53426							
GPM	Expander Board	53544							
GPM	Expander Board	53913							
Hydro Spa	Expander Board	53544							
Keys Backyard	Expander Board	53544							
Emerald/Conway	EZ1R(x)	50651			59-138-1060	59-138-1060	On Board	On Board	Can use 59-138-1033 with 58-138-1162 topside
Emerald/Conway	EZ2R(x)	50643			59-138-1060	59-138-1060	On Board	On Board	Can use 59-138-1033 with 58-138-1162 topside
Jacuzzi	F106/7R1(x)	50533	59-138-1602	58-138-1115,1116	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Jacuzzi	F108/9R1(x)	50532	59-138-1603	58-138-1102-1104	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Cal Spa	FIESTAR2(x)		No generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Cal Spa	FIESTAR3A		No generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Freeflow	FREE07R1(x)		No Generic						Heat regenerative system (no heater) Board uses special topside and operates ozone. Use board 59-138-1670 and topside 58-138-1185
Freeflow	FREE20R1(x)		59-138-1037	Special Instructions					needs overlay 10753 (58-138-1259) for topside or complete topside 54105 (58-138-1145)
Master Spas	FST Current Circuit	X551860							
Four Winds	FVS501SZR1(x)		59-138-1682		59-138-1070	59-138-1070	On Board	On Board	The original board is proprietary through Four Winds
Fort Wayne	FW100R1(x)	53065	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Fort Wayne	FW150R1(x)	53069	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Fort Wayne	FW50R1(x)	53062							Can use 59-138-1033 with 58-138-1162 topside
Leisure Bay	G2R1(x)	52326-01	59-138-1750	58-138-1700	59-138-1060	59-138-1061	59-138-1260	59-138-1262	
Gatsby	GC100R1(x)		59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Clearwater	GRDELTR1(x)	54091	59-138-1045	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Great Lakes/GPM	GVS500R1A	55032-02/53552	59-138-1680	58-138-1165	59-138-1070	59-138-1070	On Board	On Board	
Great Lakes/GPM	GVS500R2(x)	55032	59-138-1680	58-138-1165	59-138-1070	59-138-1070	On Board	On Board	
Great Lakes/GPM	GVS500R2B	55032-02/53552							
Great Lakes/GPM	GVS500SZ	55197							
Great Lakes/GPM	GVS501	54362-02							

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Great Lakes/GPM	GVS510	54376							
Great Lakes/GPM	GVS511	54374-02/54373			59-138-1070	59-138-1070	On Board	On Board	Control box number 53724 / 55198
Great Lakes/GPM	GVS511SZ	55199							
Hawkeye	H100R1(x)	51387	59-138-1025	58-138-1100	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Jacuzzi	H136R1(x)	51424	59-138-1606	58-138-1150	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Can be replaced with 58-355-3306
Hawkeye	H150R2(x)	51388*	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	*Will have to replace topside with phone connector style
Hydro Pool	H2000R1(x)	52420							Proprietary from Hydropool
Hawkeye	H25R1(x)	51391	59-138-1033	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	
Jacuzzi	H276R1(x)	51429	59-138-1604	58-138-1150	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Hawkeye	H50DR1	53187	59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	No Economy Mode
Hawkeye	H50DR2	51674	59-138-1045	See Notes	59-138-1060	59-138-1060	59-138-1260	59-138-1262	No Economy Mode
Hawkeye	H50R1(x)	51386	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Jacuzzi	H716R1(x)	50920	59-138-1605	58-138-1149	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Hydro Pool	HPL1000R1(x)	51686	59-138-1045	58-138-1147,1148,1149	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Hydro Pool	HPL100R1(x)		No generic	58-138-1148					
Hydro Pool	HPL200R1(x)	52518	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Hydro Spa	HS100	50749							
Sunset	HS100R1(x)		59-138-1031	F	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Hydro Spa	HS200	52498-01							
Hydro Spa	HS2000R2(x)	55013-01	59-138-1022		59-138-1070	59-138-1070	On Board	On Board	
HydroSpa	HS200M7R1(x)	53864*	59-138-1043	58-138-1102	59-138-1070	59-138-1070	On Board	On Board	
HydroSpa	HS200R1(x)	52498	59-138-1007	58-138-1102	59-138-1075	59-138-1070	On Board	On Board	
HydroSpa	HS200VSR(x)	55099	59-138-1684		59-138-1070	59-138-1070	On Board	On Board	
HydroSpa	HS50R1(x)	51766	59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Sunset	HS50R1(x)		59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
HydroSpa	HS55R1(x)	52520	59-138-1046		59-138-1075	59-138-1070	On Board	On Board	*This board will work if system does not have a 3rd pump.
Balboa	HTJACKR1(x)		59-138-1670		59-138-1060	59-138-1060	On Board	On Board	
Icon	ICON10R1(x)	54445/52235	59-138-1706		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Icon	ICON15R2(x)	54446/52280	No Generic						
Icon	ICON31R1(x)	54447/52297	59-138-1700	58-138-1356	59-138-1075	59-138-1070	On Board	On Board	* Can use 59-138-1007 as well per Balboa
Icon	ICON31R2(x)	54447/52297	59-138-1700	58-138-1356	59-138-1075	59-138-1070	On Board	On Board	
Icon	ICONM7R1(x)	54448/52762	59-138-1702	58-138-1102-1104	59-138-1070	59-138-1070	On Board	On Board	
Infinity	INF107R1A	54357-03	59-138-1683		59-138-1070	59-138-1070	On Board	On Board	
Artesian/Majestic	JEM400R1(x)	51230	59-138-1040	58-138-1154*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	ONLY IF NO CIRC PUMP
JEM	JEM400R1(x)	50632							
Artesian/Majestic	JEM400R2(x)	51230	59-138-1040	58-138-1154*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Only if Running One Pump

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Jetta	JET100R1(x)		59-138-1031	58-138-1102-1104	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Jacuzzi	K286R1(x)	51603	59-138-1580	58-138-1115,1116	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Keys	KEYS100CR1(x)	54357	59-138-1683	58-138-1165	59-138-1070	59-138-1070	On Board	On Board	
Keys	KEYS100DR1(x)	53795	59-138-1680	58-138-1165*	59-138-1070	59-138-1070	On Board	On Board	Also use 58-138-1143,58-138-1145
Keys	KEYS211DR1(x)	54372-01/02	59-138-1684		59-138-1070	59-138-1070	On Board	On Board	
Keys	KEYS31LEM7R1(x)		59-138-1043		59-138-1070	59-138-1070	On Board	On Board	
Leisure Bay	Kinetics Light Board	20398							
JBJ	L100	53031							
JBJ	L101R1(x)		59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Dimension One	L-1500	50717							
JBJ	L200	53034							
Dimension One	L-2000	50718							
LBJ	L200R1(x)		59-138-1035	58-138-1110	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
JBJ	L201	51296							
LBJ	L201R1(x)		No Generic						
JBJ	L90R1(x)	*	No Generic						* No longer available replaced with L90R2(x) Requires new topside 51538 also "Freeze Control" will have to be jumped for pump 2 operation.
JBJ	L90R2(x)	51595	59-138-1080	58-138-1159	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
LA Spa	LAS101R1(x)	52025	52025						
LA Spa	LAS101R2(x)	52025	52025						
LA Spa	LAS102	51620	51620						
LA Spa	LAS103R1(x)	51624-01	59-138-1671		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
LA Spa	LAS104R1(x)	51628	59-138-1672	special Instructions*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Uses Duplex Digital topside... ask customer for button configuration. NOTE:May need to adapt for different topside size.
Leisure Bay	LB102R1(x)	51793	59-138-1045	58-138-1148*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Can use with Circ Pump
Leisure Bay	LB102RR1(x)	52013	59-138-1825		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Leisure Bay	LB104R1(x)	51789	59-138-1031	58-138-1182	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Original Topside was a Deluxe Digital just find out what they are running if they need the topside only
Leisure Bay	LB124	306524							
Leisure Bay	LB500SR1(x)	54341			59-138-1070	59-138-1070	On Board	On Board	
Leisure Bay	LB500SR1(x)	53409	59-138-1758		59-138-1070	59-138-1070	On Board	On Board	
Leisure Bay	LB501SR1(x)	53353/53352/54341	59-138-1752		59-138-1070	59-138-1070	On Board	On Board	
Leisure Bay	LB50XSR1(x)	54341/53409	NLA*		59-138-1070	59-138-1070	On Board	On Board	"Per Balboa
Leisure Bay	LB70R1(x)	52973-02	58-138-2600	special Instructions*	59-138-1060				This is a complete control box for heat jacket system.
Leisure Bay	LBIS2R1(x)	52259-01	59-138-1756		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Balboa	LDE240R1(x)	53247	59-138-1039	Special Instructions*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Gas Board will take the Standard or Deluxe topsides.
Balboa	LDE240R2(x)	54175	59-138-1039		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Dimension One	LDPDR1(x)	51503	59-138-1033	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Marquis Spa	LEZURR1(x)	52149			59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Balboa	LITELDR1(x)	54115	59-138-1049	58-138-1160,1162	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Generic	LST240R1(x)	54175-01	59-138-1039		59-138-1060	59-138-1060	59-138-1250	59-138-1252	J7 jumper to B side
Balboa	LTLDBLR1(x)	54152	59-138-1049	58-138-1160,1162	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Marquis Spa	LZM2UR1(x)	600-6293	No Generic		59-138-1070	59-138-1070	On Board	On Board	
Marquis Spa	LZR1UR2B	600-6283							
Balboa	M1R1(x)	54091	59-138-1045	Special Instructions*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Any Digital Duplex topside will work Can use the Deluxe Digital Panel or the Standard Digital, or the M-Series topside
Balboa	M2/M3R1(x)	52518	59-138-1031	RETRO KIT	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Balboa	M2/M3R1(x)	54122	59-138-1048	58-138-1180,1182	59-138-1060	59-138-1060	59-138-1250	59-138-1252	If using a Deluxe, or Standard Panel refer to the 59-138-1031 Retro-Kit
Balboa	M2GAS	54122	59-138-1048	58-138-1180,1182	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Balboa	M7XXR1(x)	52076	59-138-1044	Special Instructions*	59-138-1070	59-138-1070	59-138-1250	59-138-1252	M-7 Style M2/M3 board uses M-Series topside
Majestic Spa	MAJ150R1(x)	51239	59-138-1045						
Majestic Spa	MAJ175R1(x)	50629							
Majestic Spa	MAJ200R1(x)	51233	59-138-1025	58-138-1110	59-138-1060	59-138-1060	59-138-1260	59-138-1262	This board does 120 light circ pump 1 (single speed), pump 2, blower
Majestic Spa	MAJ50R1(x)		59-138-1033	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	
Master Spas	MAS100R1(x)	53065-01	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Master Spas	MAS125R1(x)	50991	59-138-1042	58-138-1165*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Have to sale new mini oval topside 58-138-1165
Master Spas	MAS150	53609							
Master Spas	MAS200R1(x)	50973	59-138-1045	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Use pump 2 instead of Blower connection. Also sale the 58-138-1149 topside
Master Spas	MAS225R1(x)	51786	59-138-1045	special Instructions*	59-138-1060	59-138-1060	59-138-1260	59-138-1262	May need to change Label on topside from Two Jet buttons to a label with one Jet button
Master Spas	MAS25R1(x)	52000	No Generic		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Master Spas	MAS260	52532	59-138-1037	58-138-1142-1145	59-138-1070	59-138-1070	On Board	On Board	M-7 Style, Will take any duplex style topside, No Circ Pumps, otherwise they will need proprietary board from Master Spas
Master Spas	MAS300R1(x)	50975	59-138-1031	58-138-1102	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Has Circ
Master Spas	MAS400	52185							
Master Spas	MAS425R1(x)	52364	No Generic						
Master Spas	MAS460	52551							
Master Spas	MAS470	52757							
Master Spas	MAS500R1(x)	52177	No Generic						
Master Spas	MAS50R1(x)		No Generic						
Master Spas	MAS75R2(x)	53062	No Generic		59-138-1060	59-138-1060	On Board	On Board	
Artesian	MEL2000R1		No Generic						
Moon Water Spas	MOON30R1(x)		59-355-1049		59-138-1060	59-138-1060	59-138-1260	59-138-1262	Can be replaced with a 58-355-8050 Silver B
Moon Water Spas	MOON50R1(x)		59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Morgan	MOR100R1(x)	50911	59-138-1042		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Marquis Spa	MQ2KUR1A	600-6289							

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Marquis Spa	MQ2KUR2(x)	600-6289	No Generic		59-138-1070	59-138-1070	On Board	On Board	
Master Spas	MS1000	53260-02							
Master Spas	MS1500	54494							
Master Spas	MS1600	55241	No Generic	VL702S					
Master Spas	MS2000	52959							
Master Spas	MS360R1(x)	54369							
Master Spas	MS5000	54492	59-138-1022	**	59-138-1070	59-138-1070	On Board	On Board	** Topside 58-138-1050 or 58-138-1052
Master Spas	MS8000	54418/53232							
Marquis Spa	MTS2KO	53325							
Marquis Spa	MTS97R1(x)		Discontinued*						Balboa has discontinued and Marqui no longer has inventory, needs new control system.
Marquis Spa	MTS97R2(x)	51824							
Marquis Spa	MTS99R1(x)	52113							Marquis# 600-6276
Marquis Spa	MTSICCR1A	600-6224							
Marquis Spa	MTSICDRIA		No Generic						
Marquis Spa	MTSIICRID	51349	No Generic						
Marquis Spa	MTSIIR1(x)	51348	No Generic						
Marquis Spa	MTSIR1(x)	51089	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Marquis Spa	MTSIR1(x)		59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Marquis Spa	MTSUVR1C	52754							
Marquis Spa	MTSUVR1C	600-6282							
Artesian	MVS504DZR1A		No Generic						
	NAVOROR1(x)		59-138-1045*	58-138-1147	59-138-1055	59-138-1055	59-138-1260	59-138-1262	Filter select to B side and jump the pump 2
Nordic	NOR124R1(x)	50884-01	59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	If you sale board sale new topside
Nordic	NOR50R(x)	51772							
Nordic	NORVS300R1(x)	54604-01	33-54646-K	58-355-4111	59-138-1070	59-138-1070	On Board	On Board	
	NW300R1A	*	59-138-1684	58-138-1102	59-138-1070	59-138-1070	On Board	On Board	2 Pumps and a blower, they can use original topside
Cal Spa	OG2200R1(x)	52372							
Cal Spa	OG3000R1(x)	50933							
Oasis	OS2000	55101	59-138-1017						
Oasis	OS501ZR(x)		59-138-1683		59-138-1070	59-138-1070	On Board	On Board	
Clearwater	P295R1(x)		59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	Also sale topside
Clearwater	P2R1(x)	51230	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Pacific Spas	PHTLXR1(x)		59-138-1007	special Instructions*	59-138-1062	59-138-1061	On Board	On Board	May need to rewire Aux. Circuit if there is a stereo.
Phoenix	PHX15 (2000M7)	52941	59-138-1043		59-138-1070	59-138-1070	On Board	On Board	
Phoenix	PHX20R1A	52330							
Phoenix	PHX25R1A	52076							
Pacific Pool	PPW700	53150	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Pacific Pool	PPW700	53148	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Caldera	PRO3R1(x)	52380	59-138-1668		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Marquis Spa	PROMOR1(x)	50514	No Generic						

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Caldera	PROR1(x)	52083	59-138-1666	58-138-1160,1162	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Caldera	PROR2(x)	52165	59-138-1667		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
QCA	Q1002R1(x)	51316	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
QCA	Q1006R1(x)		No Generic						
QCA	Q1007R1(x)		No Generic						
QCA	Q1043R1(x)		59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
QCA	Q1043R2(x)	52518	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	Need to use
QCA	Q2002R1(x)	51777	59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
QCA	Q2004R3(x)		No Generic						
QCA	QC2000R2(x)	55015-01	No Generic						
QCA	QC3000R1A	53569							
Jacuzzi	R327R1(x)	52211	59-138-1607	58-138-1115 or 1116	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Jacuzzi	R576R1(x)	52213	59-138-1600	58-138-1160	59-138-1075	59-138-1070	On Board	On Board	
Jacuzzi	R641R1(x)	52211	59-138-1607		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Jacuzzi	R742R1(x)	52215	59-138-1601	58-138-1150	59-138-1060	59-138-1060	On Board	On Board	
Marquis Spa	RCRTNLR1	600-6254							
Marquis Spa	RCRTNLR2(x)	51504							
Marquis Spa	RCRTNLR3(x)	51800							
Marquis Spa	REC99R1A	52128							
Great Lakes/GPM	RET50R1(x)		59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Clearwater	RHYTHMR1A	52606							
Clearwater	RIP04 Mach2	53531							
Clearwater	RYTHMR1A	52532							
Leisure Bay	S2R1(x)	52259	59-138-1756		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Jacuzzi	S826R1(x)	52399	59-138-1562	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	
Saratoga	SAR100R1(x)		No Generic						
Saratoga	SAR200R1(x)	53216	59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Only if No Circ Pump
Saratoga	SAR200R2(x)	51511	59-138-1031	58-138-1102	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Only if No Circ Pump, Topside Can only be used with retro old topside different button layout
Saratoga	SAR75R1(x)		No Generic						
HydroSpa	SCS100R1(x)		59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
HydroSpa	SCS501R1(x)	54357-2	59-138-1683	58-138-1165	59-138-1070	59-138-1070	On Board	On Board	
Balboa	SERDLXR1A	54644							
Seven Seas	SEV200F.O.		59-138-1048		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Seven Seas	SEV200R1(x)	51962							
Seven Seas	SEV50R1(x)	51955	59-138-1650	58-138-1146	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Dimension One	SLCD	51707	59-138-1616						
Dimension One	SLCR1(x)	50704	59-138-1612	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	59-138-1040
Dimension One	SLCVD	51501							
Dimension One	SLCVR1(x)	51114	59-138-1614	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Dimension One	SLD	50698							

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Dimension One	SLDR1(x)	50698	59-138-1613		59-138-1060	59-138-1060	59-138-1260	59-138-1262	Also use 59-456-1030
Spa Crest	SPAC20R1A		*No Generic						* Use 56016-01 if using 54128 topside (some operations may change)
Wind River Spa	SPAE15R1(x)	53401-01	59-138-1007		59-138-1075	59-138-1071	On Board	On Board	
Icon	SPAE15R1(x)	53401-01	59-138-1007		59-138-1075	59-138-1071	On Board	On Board	
Marquis Spa	SPIRITR1(A/B)	600-6242							
Marquis Spa	SPIRITR1(C/D)	51079							
Sunrise	SRBP20R1A	56364							
Emerald/Conway	SS0D(x)	51038							
Emerald/Conway	SS1D	51040							
Emerald/Conway	SS2(x)	50669							
Emerald/Conway	SS2/SS3	50669							
Emerald/Conway	SS23BR1(x)		59-138-1040		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Emerald/Conway	SS23DR1(x)	50833	59-138-1042		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Emerald/Conway	SS3(x)	50669							
Emerald/Conway	SS300R1(x)		59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Emerald/Conway	SS3R1(x)		No Generic		59-138-1060	59-138-1060	On Board	On Board	
Emerald/Conway	SSOD	51038							
Emerald/Conway	SSR1(x)	50669	59-138-1040	58-138-1154	59-138-1060	59-138-1060	59-138-1260	59-138-1262	If have circ pump will not work
Bullfrog	STD05R1(x)	52645	59-138-1037	58-138-1148,1142,1144	59-138-1070	59-138-1070	On Board	On Board	Match topside to original size
Balboa	STDDIGR1(x)	50804	59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Sunset	SUNS25R1(X)	52702	59-138-1043	59-138-1070	59-138-1070	On Board	On Board		
Marquis Spa	SUV1UR1B	52568							*Marqui part number 600-6279
Balboa	SUVR1(x)	52532	59-138-1037	58-138-1142-1145	59-138-1070	59-138-1070	On Board	On Board	M-7 Style, Will take any duplex style topside
Southwest Spa	SW100R1(x)	52252	59-138-1046	58-138-1148	59-138-1075	59-138-1070	On Board	On Board	Could loose function on 2nd speed of second pump,58-138-1144
Southwest Spa	SW100R1(x)	52252	59-138-1046	58-138-1148	59-138-1075	59-138-1070	On Board	On Board	Could loose function on 2nd speed of second pump,58-138-1144
Southwest Spa	SW200R1(x)	52295-01	59-138-1007		59-138-1062	59-138-1061	On Board	On Board	
Swim Spa	SWIMR1(x)	50917							
Thermo Spas	TS2000R1(x)		59-138-1019		59-138-1070	59-138-1070	On Board	On Board	
Thermo Spas	TS2000R2(x)		59-138-1022	58-138-1050	59-138-1070	59-138-1070	On Board	On Board	
Thermo Spas	TS500SR1(x)		59-138-1683		59-138-1070	59-138-1070	On Board	On Board	
Leisure Bay	V124RR1(x)	52100	59-138-1754	58-138-1159					
Leisure Bay	V5120RR2(x)	52327			59-138-1060	59-138-1060	On Board	On Board	
GPM	VALUE2	52525							
GPM	VALUE3R1(x)	52569	59-138-1046		59-138-1075	59-138-1070	On Board	On Board	
Balboa	VALUER1(x)	54161	59-138-1046	Special Instructions*	59-138-1075	59-138-1070	On Board	On Board	Topside 58-138-1165, 58-138-1142-1148,A-D
Balboa	VALUM7R1(x)	52376							
Viking	VIK100R1(x)	50830	59-138-1042	58-138-1148	59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Viking	VIK50R1(x)	50827	59-138-1033	58-138-1160	59-138-1060	59-138-1060	On Board	On Board	
Viking	VKV500	54200	59-138-1680		59-138-1070	59-138-1070	On Board	On Board	

Manufacture	Chip Number	Balboa #	Horizon #	Topside	Temp	Hilimit	120V	240V	*Special Instructions*
Viking	VKV502R1(x)	54357	59-138-1683*		59-138-1070	59-138-1070	On Board	On Board	installer will need to use the blower receptacle for pump making sure to move the wire on J46 to J61 for proper conversion
Master Spas	VS 501	53620/54355							
Master Spas	VS 510 Pack	53650							
Leisure Bay	VS120RR2C	55033-02							
Leisure Bay	VS240RR2C	55036	59-138-1683		59-138-1070	59-138-1070	On Board	On Board	
Balboa	VS300AVR1(x)	55507							
Cal Spa	VS300FCR1A	55646							
Balboa	VS300FLXR1(x)	54604-01							
Balboa	VS500R1(x)	59005	59-138-1680	58-138-1142,1144	59-138-1070	59-138-1070	On Board	On Board	
Tatum	VS500TM2R2(x)	55140	59-138-1680		59-138-1070	59-138-1070	On Board	On Board	54369-03
Balboa	VS500ZR2(x)	54369	59-138-1680		59-138-1070	59-138-1070	On Board	On Board	
Balboa	VS501SZR2(x)	54378	59-138-1682	58-138-1102	59-138-1070	59-138-1070	On Board	On Board	
Balboa	VS501ZR1(x)	53268	59-138-1683		59-138-1070	59-138-1070	On Board	On Board	
Balboa	VS501ZR2(x)	54357	59-138-1683		59-138-1070	59-138-1070	On Board	On Board	
Balboa	VS510SR2(x)		59-138-1684	58-138-1102	59-138-1070	59-138-1070	On Board	On Board	
Balboa	VS510SZR1(x)	54372	59-138-1684	58-138-1102	59-138-1070	59-138-1070	On Board	On Board	
	VS510SZR2(x)		59-138-1684	58-138-1102	59-138-1070	59-138-1070	On Board	On Board	
Balboa	VS511SZ	54385			59-138-1070	59-138-1070	On Board	On Board	
QCA	VS515ZR1(x)	55477	59-355-1660		59-138-1070	59-138-1070	On Board	On Board	Generic Board Noted
Balboa	VS520SZ	55151							
Beachcomber	VS612R1(x)	55264							This board does not support an air blower
Balboa	WHRLPLR1(x)	51056	59-138-1033	58-138-1160,1162	59-138-1060	59-138-1060	On Board	On Board	
Warm Springs	WS200R1(x)		59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Warm Springs	WS75R1(x)	51903-01	59-138-1045		59-138-1060	59-138-1060	59-138-1260	59-138-1262	
Discovery Spa	ZX1000R1(x)	50726	59-138-1030	58-138-1105	59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Discovery Spa	ZX1000R2(x)	51138	*special order		59-138-1060	59-138-1060	59-138-1250	59-138-1252	*This board operates a 2spd pump 2
Discovery Spa	ZX2000R1(x)	50725	59-138-1035	58-138-1110*	59-138-1060	59-138-1060	59-138-1250	59-138-1252	Need to verify Ribbon\Phone if phone sale 59-138-1031 kit, Install Aux connector
Discovery Spa	ZX2000R2(x)	51141	59-138-1031		59-138-1060	59-138-1060	59-138-1250	59-138-1252	
Discovery Spa	ZX500DR1(x)	51133	59-138-1042		59-138-1060	59-138-1060	59-138-1260	59-138-1262	